

Instructions for the TEN(HL) Test
1. Measure the threshold for each ear in quiet (traditional pure tone audiogram) for each ear at routine frequencies
2. Set the desired noise level 10dB above in measured threshold in the same ear
3. Measure the masked threshold by re-presenting pure tones (2dB steps), while noise is playing continuously.
4. A dead region is indicated by a masked threshold that is 10 dB above the absolute threshold.